

**MONUMENT RECORD**  
State of Indiana - County of Monroe

**Section:** 5

**Township:** 9 North


**Range:** 1 West

**Corner ID:** Blm E-05

**Monument Description & Remarks:** Limestone "Broken", length 0.62ft, width 0.24ft, height 0.50ft. Survey Sign 4ft above ground at pt. B

**References On File:** Legal Survey Book 1 page 308 survey, James Spencer (1856); Michael E. Sheppard survey, Howard Halderman (2007), on file in Recorder Office cabinet S, envelope 389

RECOVERY TIE DRAWING  
Field Book 40 Page No. 38




- A - Limestone
- B - S 40° E 1.84' to Survey  
Sign on 4" wood post
- C - S 32° E 2.41' to 4ft  
limestone post
- D - N 20° W 22.04' to MAG  
nail in 9" Sugar Maple
- E - N 09° E 49.00' to MAG  
nail in 13" White Ash

Not To Scale  
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 28th day of January, 2008.

*Kevin P. Enright*



Administered by the Monroe County Surveyor Review Board

Date: 2/12/2008



Blm E-05  
01/28/2008